zrouter - Feature #29

TPLINK_ROOTFS_START, mktplinkfw -i

01/11/2012 12:19 AM - Eric Krausser

Status:	Closed		**Start date:**	01/11/2012
Priority:	Normal		**Due date:**	
Assignee:	Oleksandr Rybalko		**% Done:**	0%
Category:			**Estimated time:**	0.00 hour
Target version:			**Spent time:**	0.00 hour

Description

This patch sets TPLINK_ROOTFS_START default to 0x00200000 (fixes TODO).

When mktplinkfw was successful then information about the created firmware are shown (mktplinkfw -i fw.bin).

History

#1 - 01/11/2012 09:28 AM - Oleksandr Rybalko

Eric Krausser wrote:

> This patch sets TPLINK_ROOTFS_START default to 0x00200000 (fixes TODO).
>
> When mktplinkfw was successful then information about the created firmware are shown (mktplinkfw -i fw.bin).

Maybe better assign it to round up(by blocksize) kernel size?

#2 - 01/16/2012 12:56 AM - Eric Krausser

- Status changed from New to Closed

obsolete by Ticket 33

Files

tplink_image_rootfs_start.patch	1.15 KB	01/11/2012		Eric Krausser