

zrouter - Device Port #31

Device Port # 30 (New): BCM5354

BCM5354 fix switch

01/12/2012 09:45 PM - Oleksandr Rybalko

Status:	New	Start date:	01/12/2012
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
one port not pass data possible cause - portbased VLAN, so need proper reset or better full config dump			

History

#1 - 01/12/2012 09:48 PM - Oleksandr Rybalko

- Subject changed from fix switch to BCM5254 fix switch

#2 - 01/12/2012 09:49 PM - Oleksandr Rybalko

- Subject changed from BCM5254 fix switch to BCM5354 fix switch