

## Issues

| #  | Project                  | Tracker     | Status | Priority | Subject  | Assignee          | Updated             |
|----|--------------------------|-------------|--------|----------|--|-------------------|---------------------|
| 32 | zrouter                  | Device Port | Closed | Normal   | BCM5354 fix UART                                       | Alexander Mityaev | 04/04/2012 02:07 PM |
| 2  | zrouter                  | Feature     | Closed | Normal   | move bot to zrouter.org                                | Oleksandr Rybalko | 05/05/2011 08:46 AM |
| 21 | FreeBSD HEAD for ZRouter | Bug         | Closed | Normal   | Fix static/dynamic kenv                                | Oleksandr Rybalko | 03/02/2012 10:26 AM |
| 23 | zrouter                  | Feature     | Closed | Normal   | Test and rework/revert RSPRO EntryPoint test patch     | Oleksandr Rybalko | 03/02/2012 10:23 AM |
| 14 | zrouter                  | Bug         | Closed | Normal   | fix mkulzma dependency                                 | Oleksandr Rybalko | 12/20/2011 11:48 PM |
| 3  | zrouter                  | Feature     | New    | High     | ZRouter Birthday                                       |                   | 08/16/2011 09:02 AM |
| 19 | zrouter                  | Feature     | New    | High     | remove ISC dhcpd in favor of dnsmasq and base dhclient |                   | 12/11/2011 01:08 PM |
| 9  | zrouter                  | Device Port | New    | Normal   | RT3052F  | Oleksandr Rybalko | 10/28/2011 01:34 PM |
| 1  | zrouter                  | Feature     | New    | Normal   | #zrouter bot   | Oleksandr Rybalko | 09/05/2011 11:08 PM |
| 11 | zrouter                  | Device Port | New    | Normal   | DAP-1350   |                   | 10/28/2011 01:34 PM |
| 13 | zrouter                  | Feature     | New    | Normal   | Web you TreeView enhancement                           |                   | 11/08/2011 06:08 PM |
| 20 | FreeBSD HEAD for ZRouter | Feature     | New    | Normal   | Fill sysctl variables with SoC/Board/etc values        |                   | 12/11/2011 01:12 PM |
| 22 | zrouter                  | Support     | New    | Normal   | MBR/GPT for i386/amd64 image                           |                   | 12/11/2011 10:08 PM |
| 31 | zrouter                  | Device Port | New    | Normal   | BCM5354 fix switch                                     |                   | 01/12/2012 09:49 PM |
| 30 | zrouter                  | Device Port | New    | Normal   | BCM5354  |                   | 04/04/2012 02:07 PM |
| 7  | zrouter                  | Device Port | New    | Normal   | AR7242   |                   | 10/24/2011 09:41 PM |
| 6  | zrouter                  | Device Port | New    | Normal   | AR7241   |                   | 10/24/2011 09:41 PM |
| 5  | zrouter                  | Device Port | New    | Normal   | DIR-615_E4   |                   | 10/24/2011 09:26 PM |
| 4  | zrouter                  | Device Port | New    | Normal   | AR7240   |                   | 10/24/2011 09:26 PM |
| 8  | zrouter                  | Device Port | New    | Normal   | RT3050F  |                   | 10/24/2011 09:42 PM |
| 10 | zrouter                  | Device Port | New    | Normal   | DIR-620  |                   | 10/28/2011 01:34 PM |
| 12 | zrouter                  | Feature     | New    | Low      | Wiki writing/fixing anybody want to help?              |                   | 10/28/2011 11:01 PM |